

Environmental and Social Monitoring Second Report

Project Number: 48368-001
August 2017

MYA: Myingyan Natural Gas Power Project Part 2

Prepared by Environ Myanmar Co Ltd.

The environment and social monitoring report is a document of the borrower. The views expressed herein do not necessarily represent those of ADB's Board of Directors, Management, or staff, and may be preliminary in nature. Your attention is directed to the "Terms of Use" section of this website.

In preparing any country program or strategy, financing any project, or by making any designation of or reference to a particular territory or geographic area in this document, the Asian Development Bank does not intend to make any judgments as to the legal or other status of any territory or area.

APPENDIX 1 – SITE VISIT PHOTO LOG



Photo 1: Nyaung Hla “jetty”, which is no longer used by the Project




Photo 2: Equipment colour-coding to demonstrate maintenance and fitness-for-use

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014



Photo 3: Dust suppression on site roads



Photo 4: Trucks fitted with covers that are used when conveying soil and dusty materials

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014

RAMBOLL ENVIRON



Photo 5: Vacuum tanker collecting sewage from septic tank at JEM camp



Photo 6: Wastewater disposal pit, reportedly used for disposal of sanitary wastewater

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014

RAMBOLL ENVIRON



Photo 7: Evidence of wastewater disposal on soil adjacent to pit



Photo 8: Screen on kitchen wastewater discharge at JEM camp

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014





Photo 9: Surface water collection pit



Photo 10: Bund appears to have less than 110% of the tank capacity

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014

RAMBOLL ENVIRON



Photo 11: Cracks in bund wall around diesel tank at Concrete Batching Plant



Photo 12: Drainage pipe from bunded area (bottom left of photo) had an open valve

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014

RAMBOLL ENVIRON



Photo 13: Several drainage holes in bund wall around diesel tank in SDCI area (most are obscured by the drums)



Photo 14: Soil contamination outside diesel tank in SDCI area

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014

RAMBOLL ENVIRON



Photo 15: Portable generator without a drip tray



Photo 16: Physically restated land around transmission tower in a farmer's field

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014





Photo 17: Poor containment of food waste



Photo 18: Inadequate containment of general waste

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014

RAMBOLL ENVIRON



Photo 19: Medical waste disposal area in landfill site



Photo 20: Medical waste mixed with general waste on surface of landfill

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014





Photo 21: Waste falling from landfill into ephemeral stream bed adjacent to landfill site



Photo 22: Excellent housekeeping in JEM maintenance warehouse

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014

RAMBOLL ENVIRON



Photo 23: Unlabelled drums



Photo 24: Oil drum in poor condition, with adjacent ground staining

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014

RAMBOLL ENVIRON



Photo 25: Project CGM suggestion box outside Aye Village



Photo 26: School in Tha Pyay Thar

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014

RAMBOLL ENVIRON



Photo 27: Outdoor classroom at school in Tha Pyay Thar



Photo 28: New drainage system at Min Dhama camp

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014

RAMBOLL ENVIRON



Photo 29: New drainage storage tank at Min Dhama camp




Photo 30: Room with six occupants at JEM workers camp

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014

RAMBOLL ENVIRON



Photo 31: Room with four occupants at JEM workers camp



Photo 32: New zinc roof with drainage at JEM workers camp

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014

RAMBOLL ENVIRON



Photo 33: Double room at Bedok workers camp




Photo 34: Room with single occupant at Bedok workers camp

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014

RAMBOLL ENVIRON



Photo 35: Men's dormitory at Bedok workers camp



Photo 36: Exercise room at the Bedok camp

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014

RAMBOLL ENVIRON



Photo 37: New zinc roof at the Min Dhama workers camp



Photo 38: Unskilled workers housing at the Min Dhama workers camp

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014

RAMBOLL ENVIRON



Photo 39: Women's rural bathing area at the Min Dhama workers camp



Photo 40: Power Pole along the river water supply pipeline

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014

RAMBOLL ENVIRON



Photo 41: Farmer and daughter who received compensation for corn and onion crops



Photo 42: Foundation for new house built with farmer's crop compensation

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014

RAMBOLL ENVIRON



Photo 43: Lady with Small Shop next to the Tea House



Photo 44: Co-Owner of the Tea House

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014

RAMBOLL ENVIRON



Photo 45: Rebuilt Tea House with two Power Poles



Photo 46: Squatters' New Fence

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014

RAMBOLL ENVIRON



Photo 47: HSE Safety Board and WGM suggestion box at Project Site

Title: Second Lenders' IESC Monitoring Report
Site: Myingyan CCPP, Myanmar

Date: August 2017
Project: MM110014